This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

AMENDMENT TO THE SPECIFICATION

Please replace the paragraph beginning on page 26, line 7 and ending on page 26, line 18 with the following paragraph:

Drive shafts 360 and 362 are driven by motor 142 under control of controller 140 to rotate supply and take-up spools 122 and 124 as desired to control the position of ribbon 120 and its panels relative to printhead 106, as well as to provide tension in ribbon 120. Drive shafts 360 and 362 each preferably includes longitudinal ridges 364—369 (FIG. 4) that are received between corresponding longitudinal ridges 367 of supply and take-up spool cores 322 and 324, shown in FIG. 16. Ridges 364—369 intermesh with ridges 367 to prevent slippage between shafts 360 and 362 and supply and take-up spools 122 and 124.